

#### State of Utah

## Department of Natural Resources

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director



GARY R. HERBERT Lieutenant Governor

August 23, 2006

Palmer Helsten Integrity Remodeling and Const. Inc. 13752 South 7300 West Herriman, UT 84096

Subject: <u>Deficient Notice of Intention to Commence Small Mining Operations</u>, <u>Integrity Remodeling and Construction</u>, <u>Inc.</u>, <u>Palmer Helsten</u>, <u>M0490057</u>, Task ID# 1514, Utah County, Utah

Dear Mr. Helsten:

The Notice of Intent to Commence Small Mining Operations (NOI), received by the Division August 10, 2006, concerning the proposed small mining project located in Township 11 South, Range 2 West, SLBM, Utah County, Utah is incomplete. The following information is required:

### Rule R647-3-105 - Project Location and Map:

Please provide a detailed map of the proposed 5-acre permit area, identifying where mining will take place, where materials (rock, overburden, topsoil etc.) will be stockpiled. This map should be of sufficient scale to show this detail, and at a minimum of 1inch=200 feet.

Of the two maps provided, one shows approximately 5.75 acres of disturbance and the other identifies over 11 acres.

Please provide a complete legal description of the site to the nearest 1/4, 1/4 section. The map provided includes a legal description of the subdivision plat, not the location of mining operations proposed by your notice.

#### Rule R647-3-106 - Operation Plan:

Please provide a description of how the area will be mined (how will overburden/topsoil be removed and stockpiled? To what depth will excavation occur? etc.

Page 2 Palmer Helsten M0490057 August 28, 2006

Please describe the length and width of the future access road. The acreage involved with the new road will be considered part of the mining disturbance.

#### Rule R647-3-110 - Variances:

The Notice did not indicate whether any variances are requested, or not. Please note, variances must be approved in advance. Please review this section and provide the necessary information needed if you believe any variances are warranted for this operation.

On Aug 22, 2006 the Division received the signed reclamation contract and \$10,000 cashier's check for reclamation surety. The Division can not determine if this amount is adequate until the above information is provided. In reply, <u>please</u> refer to file number M0490057. Thank you for your cooperation.

Sincerely,

Susan M. White

Mining Program Coordinator Minerals Regulatory Program

Sunn. White

 $SMW:LK:jb \\ P:\GROUPS\MINERALS\WP\M049-Utah\S0490057-PalmerHelstenPit\final\Rev1-08232006.doc$